go displays

Linx Display Board



Scan our QR code to view the full assembly video



You'll receive loop nylon panels, poles and circular bases.



Step 1

Take 1 base and pole and screw the pole into the base until tight and secure.

Complete for both poles & bases.



Step 2

Lay the pole down and slide 1 clip down each pole, right down to the base.



Step 3

Fix 1 clip to the top of each pole with the screw located at the side. This will secure the clip at this height.

go displays



Step 4

Place the bottom of the board into one of clips which is sitting at the base. Slide the board up the pole with the bottom fitting.



Step 5

Slide the board up to the top and slot the top clip into the top of the display board.



Step 6

Once the board is sat in both clips, tighten the bottom clip on to the pole with the screw hidden in the side.

Step 7

Repeat the process to ensure all 4 clips have been clipped into the board and the screws have been tightened to the pole.

