

Exhibit Exhibition Stand Panels



Scan our QR code to view assembly video

Each panel is supplied in an individual branded box.









Step 1

Take the first cross bar and attach both the corner connectors by sliding into the frame and stopping once the push pin clicks into place.

Step 2

Insert an upright section onto the left & right connector. Push the uprights down until the push pin clicks through the hole in the upright.







Step 4 Once both ends are in the accessory fitting slots, turn the bracing bar towards you to lock in place.

Step 3

Select the bracing bar and slot into the accessory fitting slots on both uprights, at the same level.

Repeat steps 1-4 with the remaining cross bar, uprights and bracing bar.

Once completed, you'll have x2 half panels.



Step 5

You[']ll be left with 2 straight connectors. Take 1 half of the frame and push the connector until the push pin clicks through the hole in the upright frame section.



Step 6

Use your foot to steady the bottom section and lift the top section to slot onto the straight connectors. The push pin will click into place.

Repeat steps 1-6 for all standard panels as part of your exhibition stand kit.






Exhibit Exhibition Stand - Attaching Stability Feet

Feet can be attached either to the ends or middle of your Exhibit Panels.



Step 1

Place the panel on top of the foot/feet, making sure the cross bar labelled 721E12.970B is at the bottom of the frame,




Step 2

Line up the holes in the panel with the holes in the base and thread 2 screws through.



Step 3 Tighten in place with a 5mm allen key.




Step 4 Line up the holes in the panel with the holes in the base and thread 2 screws through.



The same processed is used when attaching 2 stability feet.





Step 5

Adjustable feet are built into the each panel and can be adjust with a 5mm allen key. Adjustments may be needed on uneven flooring to ensure panels

line up.

Exhibit Exhibition Stand - Connecting panels together (Straight configuration)



go displays

Step 1

To connect the panels together, position next to each other so the frames are touching.





Step 2

Secure at the top and bottom of the panel with the supplied screws, tightening in place with a 5mm allen key.



Exhibit Exhibition Stand - Connecting panels together (L Shape Configuration)



Step 1

Place an L shape bracket on the floor and lift 1 panel to sit on top of the bracket.



Step 4

Using a ladder and reaching the top of the stand, attach an L bracket into the 90 degree angle and use a 5mm allen key to secure.



Step 2

Match the holes on the bottom cross bar with the holes on the L bracket. Thread through 2 screws & tighten with 5mm allen key.



Step 3

Position the 2nd panel, to create a 90 degree angle and follow the same fixing process as step 2.

Exhibit Exhibition Stand - Attaching Panels



Step 1

Take the panels out of the box and keep in the rolled form. Start at the top of the panel, lining up the corner of the graphic with the corner of the frame.



Step 2

Unroll the panel as you connect the pre-fitted hook and loop tape together down the length of the panel.



Step 3 Press down on all 4 sides to ensure the panels are securely fitted.

Repeat all 3 steps until the full Exhibit Panel Kit has a fitted graphic panel.